


FIG. 2






FIG. 3




FIG. 2A




FIG. 5

602 604 606 608 600 600 612 614

Server Name	E	Date/Time	Source	Category	Description	Details
baba	1	11:29:16 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	2	11:29:17 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	3	11:34:38 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	4	11:34:39 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	5	11:36:36 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	6	11:36:38 AM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	7	2:04:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	8	2:05:14 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	9	2:05:17 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	10	2:05:18 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	11	2:06:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	12	2:07:35 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	13	2:07:36 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	14	2:07:37 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	15	2:08:49 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	16	2:09:28 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	17	3:01:10 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	18	3:01:27 PM Thu. September 4, 1997	Power Supply Alert	serious	Power Supply identified by the...	Please ch...
baba	19	6:36:25 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	20	6:36:35 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	21	6:44:04 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	22	6:44:06 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	23	6:44:55 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	24	6:44:57 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...
baba	25	6:48:42 PM Thu. September 4, 1997	Slot Fan Alert	serious	The speed of the I/O slot fan i...	Please ch...

NetPBM server detected on network dome

FIG. 6





FIG. 7






FIG. 9

1000

ALERT MANAGER MODULE 202

1002

1004

ALERT MANAGER TABLE

SERVER 1 (NAME)

CPU ALERT DESCRIPTION: "CPU IDENTIFIED BY THE CPU NUMBER FAILED BECAUSE OF HIGH TEMPERATURE AND/OR LOW POWER"

NOTIFY YES/NO

SYSTEM BOARD FAN ALERT

NOTIFY YES/NO

TEMPERATURE SENSOR ALERT

NOTIFY YES/NO

POWER SUPPLY ALERT

NOTIFY YES/NO

ADAPTER ALERT

NOTIFY YES/NO

CANISTER ALERT

NOTIFY _____

SLOT FAN ALERT

NOTIFY _____

CANISTER FAN ALERT

NOTIFY _____

SERVER 2 (NAME)

CPU ALERT

NOTIFY YES/NO

•

•

•

(TYPICAL METHODS)

CALL ALERT MANAGER DIALOG MODULE 216

CALL ALERT FLASH DIALOG MODULE 218

1006

FIG. 10

2025 RELEASE UNDER E.O. 14176




FIG. 11




FIG. 12